

UNITED STATES PATENT AND TRADEMARK OFFICE



UNITED STATES DEPARTMENT OF COMMERCE United States Patent and Trademark Office Address: COMMISSIONER FOR PATENTS P.O. Box 1450 Alexandria, Virginia 22313-1450 www.uspto.gov

APPLICATION NO.	FILING DATE	FIRST NAMED INVENTOR	ATTORNEY DOCKET NO.	CONFIRMATION NO	
10/677,517	10/02/2003	Craig R. McCrea	CM-1-am-mv	8243	
7590 05/18/2005			EXAM	EXAMINER	
Michael I. Kroll			NGUYEN, HOANG M		
171 Stillwell Lane Syosset, NY 11791			ART UNIT	PAPER NUMBER	
,			3748		
		DATE MAILED: 05/18/2005			

Please find below and/or attached an Office communication concerning this application or proceeding.

		&			
	Application No.	Applicant(s)			
	10/677,517	MCCREA, CRAIG R.			
Office Action Summary	Examiner	Art Unit			
	Hoang M Nguyen	3748			
The MAILING DATE of this communication app Period for Reply	ears on the cover sheet with the c	correspondence address			
A SHORTENED STATUTORY PERIOD FOR REPLY THE MAILING DATE OF THIS COMMUNICATION. - Extensions of time may be available under the provisions of 37 CFR 1.13 after SIX (6) MONTHS from the mailing date of this communication. - If the period for reply specified above is less than thirty (30) days, a reply - If NO period for reply is specified above, the maximum statutory period with the set or extended period for reply will, by statute, Any reply received by the Office later than three months after the mailing earned patent term adjustment. See 37 CFR 1.704(b).	36(a). In no event, however, may a reply be tin within the statutory minimum of thirty (30) day will apply and will expire SIX (6) MONTHS from cause the application to become ABANDONE	nely filed s will be considered timely. the mailing date of this communication. D (35 U.S.C. § 133).			
Status		·			
1) Responsive to communication(s) filed on	_·				
2a) ☐ This action is FINAL . 2b) ☑ This action is non-final.					
3) Since this application is in condition for allowance except for formal matters, prosecution as to the ments is					
closed in accordance with the practice under E	Ex parte Quayle, 1935 C.D. 11, 4	53 O.G. 213.			
Disposition of Claims					
4) □ Claim(s) 1-25 is/are pending in the application. 4a) Of the above claim(s) is/are withdray 5) □ Claim(s) is/are allowed. 6) □ Claim(s) 1-25 is/are rejected. 7) □ Claim(s) is/are objected to. 8) □ Claim(s) are subject to restriction and/o	wn from consideration.				
Application Papers					
9) The specification is objected to by the Examine	r.				
10)☐ The drawing(s) filed on is/are: a)☐ acc					
Applicant may not request that any objection to the	• • • • • • • • • • • • • • • • • • • •	` '			
Replacement drawing sheet(s) including the correct 11) The oath or declaration is objected to by the Ex		•			
	difficient total the attached office	7,00,011 01 1011111 1 0 102.			
Priority under 35 U.S.C. § 119					
 12) Acknowledgment is made of a claim for foreign a) All b) Some * c) None of: 1. Certified copies of the priority document: 2. Certified copies of the priority document: 3. Copies of the certified copies of the priority application from the International Bureau * See the attached detailed Office action for a list 	s have been received. s have been received in Applicati rity documents have been receive u (PCT Rule 17.2(a)).	on No ed in this National Stage			
Attachment(s)					
1) X Notice of References Cited (PTO-892)	4) Interview Summary	(PTO-413)			
2) Notice of Draftsperson's Patent Drawing Review (PTO-948)	Paper No(s)/Mail D	ate Patent Application (PTO-152)			
3) Information Disclosure Statement(s) (PTO-1449 or PTO/SB/08) Paper No(s)/Mail Date	6) Other:	atent Application (F 10-192)			

Application/Control Number: 10/677,517 Page 2

Art Unit: 3748

Claims 1-25 are rejected under 35 U.S.C. 101 because the disclosed invention is inoperative and therefore lacks utility. There are two critical aspects of this invention that may make this device inoperative.

- 1) The Stirling engine starts out at the vertical position with about 90 degrees angle to the horizontal plane as shown in figure 1A. At this position, no matter if the piston keeps moving up and down, there is no force in the horizontal direction to cause the cylinder of the engine to rotate. Figures 1C and 1D show the same problem because the cylinder is at the vertical position.
- 2) It does not seem like the output force can be transferred to the output shafts because even if the cylinder rotates, the pivot clamps moves, not the shafts. If both move at the same time, it's difficult for the cylinder to rotate.

Claims 1-25 are also rejected under 35 U.S.C. 112, first paragraph. Specifically, since the claimed invention is not supported by either a well asserted utility or a well established utility for the reasons set forth above, one skilled in the art clearly would not know how to use the claimed invention.

The prior art made of record and not relied upon is considered pertinent to applicant's disclosure. Parr, Dibrell et al, Hsiao, McClung disclose walking beams with Stirling engines.

Art Unit: 3748

Any inquiry concerning this communication or earlier communications from the Examiner should be directed to Examiner Nguyen whose telephone number is (571) 272-4861. The examiner can normally be reached on Tuesday--Friday from 12:30 AM to 10:00 PM.

If attempts to reach the examiner by telephone are unsuccessful, the examiner's supervisor, Thomas Denion, can be reached on (571)-272-4859. The fax phone number for the Examiner is (703) 872-9306 for regular communication, and (703) 872-9303 for after final communication.

Any inquiry of a general nature or relating to the status of this application should be directed to the Group receptionist whose telephone number is (571) 272-3700.

HOANG NGUYEN PRIMARY EXAMINER ART UNIT 3748

Hoang Minh Nguyen 5/12/05